



# **Ruijie RG-WLAN Series Access Points**

## **RGOS Release Notes, 11.9(6)B1**

---

**Release Date: Sep 21<sup>st</sup>, 2020**

## Contents

This document includes the following sections:

- [Basic Information](#)
- [Hardware Supported](#)
- [New Features](#)
- [Resolved Issues](#)
- [Upgrade Packages](#)
- [Upgrade/Downgrade Tips](#)

## Basic Information

Table 1 lists the basic information of the current release.

**Table 1 Basic Information of the Current Release**

<b>Current Release</b>	RGOS 11.9(6)B1
<b>Previous Release</b>	RGOS 11.9(4)B1
<b>Applicable Product</b>	<b>Indoor AP:</b> AP820-L(V2) v1.x, AP840-I v1.x, AP180 v2.x <b>Outdoor AP:</b> AP680(CD) v1.x  <b>AC Version:</b> RGOS 11.9(5)B1 and later
<b>Category</b>	Official release

Use the **show version** command to display information about the software version.

```
Ruijie#sh ver detail
System description      : Ruijie Indoor AP820-A(X) (802.11a/n/ac/ax and 802.11b/g/n/ax) By
Ruijie Networks.
System start time       : 1970-01-01 08:00:00
System uptime           : 0:00:00:54
System hardware version : 1.00
System software version : AP_RGOS 11.9(6)B1, Release(07201412)
System patch number     : NA
System software number  : M12025608142020
System serial number    : 1234567890123
System boot version     : 2017.09.4f16ab4(200805)
System core version     : 2.6.32.eaebc51bc2a288
```

### Release Number Description

Software number M20015609252015 indicates 20:01:56 on September 25, 2015.



Release number is formatted as AABBCDD.

AA indicates year. 01 stands for 2014, 02 for 2015 and so on.

BB indicates month. 13 stands for January, 14 for February and so on.

CC indicates date.

DD indicates time in 24-hour format, e.g., 16 stands for 4pm.

Take release number 02212520 for example. It indicates 8pm on September 25, 2015.

## Hardware Supported

Table 2 shows the hardware supported by the RGOS 11.9(6)B1.

**Table 2 Supporting Hardware Models**

Hardware Model	Version	Description
AP820-L(V2)	1.x	Indoor Access Point, one 10/100/1000M WAN Port, Built-in Antenna, Dual-Radio, Dual-Band, 2.4 G + 5 G or 5.2 G+5.8 G, 2x2 + 2x2 Spatial Streams, 802.11a/b/g/n/ac/ax.
AP840-I	1.x	Indoor Access Point, two 10/100/1000M WAN Ports, one 1Gbps IoT Port, Built-in Antenna, Dual-Radio, Dual-Band, 2.4 G + 5 G, 2x2 + 4x4 Spatial Streams, 802.11a/b/g/n/ac/ax.
AP180	2.x	Indoor Access Point, one 10/100/1000M WAN Port, four 10/100/1000M LAN Ports, Built-in Antenna, Dual-Radio, Dual-Band, 2.4 G + 5 G, 2x2 + 2x2 Spatial Streams, 802.11a/b/g/n/ac/ax.
AP680(CD)	1.x	Outdoor Access Point, one 10/100/1000M WAN Port, one 10/100/1000M SFP Port, Built-in Antenna, Dual-Radio, Dual-Band, 2.4 G + 5 G, 2x2 + 2x2 Spatial Streams, 802.11a/b/g/n/ac/ax.



### Note

The hardware version number is rounded to the first decimal place. The numeral in the second decimal place does not change the supporting release.

## New Features

**PPPoE, NAT and IPSec VPN**

<b>Description</b>	Support PPPoE(FIT/FAT), NAT, IPSec VPN and other gateway functions on Wi-Fi6 series products.
<b>CLI command</b>	N/A

**802.11r**

<b>Description</b>	Support 802.11r on Wi-Fi6 series products.
<b>CLI command</b>	N/A

**Separate ARP Request Broadcast on Ruijie Cloud**

<b>Description</b>	Separate ARP broadcast on Ruijie Cloud.
<b>CLI command</b>	<p>On Ruijie Cloud, two clients in the same network segment are not allowed to send ARP packets to each other.</p> <ol style="list-style-type: none"> <li>1. Enable separating ARP packets  Ruijie(config)#data-plane arp-control enable</li> <li>2. Configure separating ARP packets  Ruijie(config)#data-plane arp-control vlan 1 trusted-host 1.1.1.1</li> </ol> <p>When a client in VLAN 1 sends ARP request, it will only trust and receive the response from 1.1.1.1.</p>

**WDS Encryption**

<b>Description</b>	Support WDS encryption on AP680(CD)
<b>CLI command</b>	<p>The root bridge sends out encrypted signals whose encryption is the same with that of common signal:</p> <pre>security wpa/rsn enable security wpa/rsn ciphers aes enable security wpa/rsn akm psk enable security wpa/rsn akm psk set-key ascii xxx</pre> <p>Non-root bridge encryption command:</p> <p>The <b>non-root bridge encryption</b> command should be run in radio configuration mode.</p> <p>Now only wpa/wpa2 aes psk are supported.</p> <ol style="list-style-type: none"> <li>1. wpa  bridge security wpa ciphers aes akm psk key ascii xxx(xxx indicate the encryption key)</li> <li>2. wpa2(rsn encryption)</li> </ol>

bridge security rsn ciphers aes akm psk key ascii xxx
---

## Resolved Issues

Table 3 shows the fixed bugs based on RGOS 11.9(6)B1.

**Table 3 Fixed Bugs**

No.	Bug Description
1	When WIDS black/whitelist is enabled, uplink AMSDU aggregate packets may lose.
2	Wi-Fi6 clients may be not able to access the Internet.

## Upgrade Packages

**Table 4.1 AP820-L(V2)**

Applicable Product	File	File Size	MD5
AP820-L(V2) v1.x	AP_RGOS11.9(6)B1_S2X2-05_07201411_install.bin	24,697,968 bytes	bbb9feeb6ffea43f1b5971d4d4f4dda8

**Table 4.2 AP840-I v1.x**

Applicable Product	File	File Size	MD5
AP840-I v1.x	AP_RGOS11.9(6)B1_S2X4-01_07201411_install.bin	27,212,919 bytes	fc77568e05ff893c31460f0dbaf7cbfb

**Table 4.3 AP180 v2.x**

Applicable Product	File	File Size	MD5
AP180 v2.x	AP_RGOS11.9(6)B1_S2X2-09_07201411_install.bin	22,803,751 bytes	6ad4451fc6a69cff833b3b5c085aef83

**Table 4.4 AP680(CD) v1.x**

Applicable Product	File	File Size	MD5
AP680(CD) v1.x	AP_RGOS11.9(6)B1_S2X2-06_07201411_install.bin	25,127,264 bytes	83475e6dfb75354199e58d37d19305ad

## Upgrade/Downgrade Tips

The following are some tips for upgrading the RG-WLAN Series Access Point RGOS 11.9(6)B1:

- Use the **show version** command to check the current firmware before upgrade/downgrade. Select proper upgrade/downgrade mode according to the current firmware and the target firmware.
- During the upgrade and downgrade, pay attention to the prompt messages. If failures occur, please save the log and contact us for technical assistance.
- During the upgrade and downgrade, it is recommended you not power off or reset the system, or plug/unplug any module.
- Use the **show version** command to check the firmware after the upgrade/downgrade.