

ZYXEL

Software Release Note

NebulaFlex Switch XS3800 Series

Date: Jul. 15, 2022

Zyxel NebulaFlex Switch XS3800 Series

V4.80(ABML.0)C0 Release Note

Date: Jul. 15, 2022

This document describes the features in the XS3800 series for its 4.80(ABML.0)C0 release.

XS3800 series is a hybrid switch with NebulaFlex technology to support operation in either Standalone mode or Nebula cloud management mode.

Supported Platforms

| Support Platform | Firmware version | Boot Version |
|------------------|------------------|--------------------|
| Zyxel XS3800-28 | V4.80(ABML.0)C0 | V3.00 06/14/2019 |

New Feature and Enhancements

| New Feature and Enhancements | Cloud | Standalone |
|--|-------|------------|
| 1. Renovate Web GUI layout for better usability of Switch management. | V | V |
| 2. Support search bar on local Web GUI. | V | V |
| 3. Strengthen security for network management with built-in notification in case of abnormal login attempt. | V | V |
| 4. Support Flex link as a pair of Layer 2 interfaces for link redundancy. | - | V |
| 5. Support "Account Security" option on WEB GUI to encrypt admin/user account password and options to display user/AAA/SNMP credentials. | V | V |
| 6. Nebula Switch supports IP source guard (IPSG) to prevent IP spoofing attacks. | V | - |
| 7. Support Auto configuration recovery on Nebula to prevent loss connection with NCC by misconfiguration. | V | - |

| New Feature and Enhancements | Cloud | Standalone |
|---|--------------|-------------------|
| 8. Intuitive Cloud connection status with help message. | V | V |
| 9. Unlock CLI to support full configuration in cloud mode (managed switches only). | V | - |
| 10. Nebula Switch supports SSH connection to access command line for advanced features. | V | - |
| 11. Support OSPF network type broadcast/point-to-point. | - | V |
| 12. Support redistributing "Connected" interface subnet to OSPF database directly. | - | V |
| 13. Support IPv6 Interface Route Prefix to 128. | - | V |
| 14. Allow to change the IP address from DHCP to static type directly for Layer 3 switch. | V | V |
| 15. Support user uses "setup.zyxel.com" directly to access local web GUI. | V | V |
| 16. Support auto STP path cost which determines path cost by the port's current link speed. | - | V |
| 17. Strengthen user security with the encryption of TACACS+ & Radius shared secret. | - | V |
| 18. Extend RADIUS server support range from IPv4 to IPv6. | - | V |
| 19. Enhance Guest VLAN to isolate broadcast packets between VLANs. | - | V |
| 20. Supports IP failover function by setting backup default route. | - | V |
| 21. Support Smart Fan Control. | V | V |
| 22. SNMP is disabled by default. | V | V |
| 23. Disable insecure_SSL_cipher of HTTPs to enhance security. | V | V |
| 24. The year of Time Range page starts with current system time. | V | V |

Bug fix

| Bug fix | Cloud | Standalone |
|---|-------|------------|
| 1. [eITS#210401140] The Port description of neighbor switch has unrecognized character. When NCC server gets LLDP information from Nebula switch, the connection between Nebula switch and NCC server will be disconnected. | V | - |
| 2. [eITS#210500522] Every time, switch updates igmp-snooping client statistic may cause reboot due to memory leak. | V | V |
| 3. [eITS#210501222] Web GUI login page may encounter display error or problem to display proper login page when Switch is under concurrent TCP ping task. | - | V |
| 4. [eITS#210900900] Nebula CC may display incorrect ports' TX/RX data. | V | - |
| 5. [eITS#210701300] Switch supports IGMPv3 packet for source-type of "block source" parameter. | - | V |
| 6. [eITS#211100996] Compound authentication loose mode combined with MAC-authentication should allow traffic to proper VLAN upon authentication approval, it currently moves all traffic to guest VLAN regardless of authentication status. | - | V |
| 7. [eITS#220400279] Modify switch DNS re-query behavior to prevent NCC displays 0.0.0.0 LAN IP address and | V | - |

| Bug fix | Cloud | Standalone |
|--|-------|------------|
| online status on switch monitor page. | | |
| 8. [eITS#220400686] Allow to configure an existed IPv4 address to a different VLAN via wizard on Networked AV mode. | - | V |
| 9. [eITS#220500960] Enabling and disabling 802.1x or Guest VLAN on an unauthenticated or empty switch port causes all authenticated ports to disconnect. | V | V |

Known Issue

| Known Issue | Cloud | Standalone |
|---|-------|------------|
| 1. ACL policy rule's priority and 802.1p queue (in Basic setting -> Port Setup) action should be combined to take effect. | - | √ |
| 2. ACL cannot support configuration of layer 4 socket port range when using IPv6. | - | √ |
| 3. Fiber ports 21-28 cannot support port speed mode: Auto-Negotiation 1000M. | √ | √ |
| 4. SFP transceiver incompatible with delta LCP-1250RJ3SR-S. | √ | √ |
| 5. Check illegal ARP packets and illegal IP packets should be dropped while enable IPSG, port security and LACP. | - | √ |
| 6. DHCP discover packets would be incorrectly flooded to other ports in case of enabling ARP Inspection + DHCP Snooping + Ingress Check + Port Security simultaneously. | - | √ |
| 7. Alignment error packet count error on boundary packet size. | √ | √ |
| 8. Queuing method using WRR or WFQ queue based traffic rate is correct, but multiple traffic mapping to same queue, those traffic rate won't be balanced. | √ | √ |
| 9. Change the IP source guard mode, the ARP Inspection Filter table cloud not be flushed. | - | √ |
| 10. 10G port throughput can't reach full rate when the traffic is go through stacking port because control packets occupy few bandwidth. | - | √ |
| 11. Plugin 1000T transceiver without cable, port will link up when set to 1000-full. | √ | √ |

| Known Issue | Cloud | Standalone |
|--|--------------|-------------------|
| 12. The cable diagnostic result may not be accurate. | V | V |

Limitation of Settings:

| Limitation of Setting | Cloud | Standalone |
|--|--------------|-------------------|
| 1. VLANIQ static entry | 1k | 4k |
| 2. Static MAC forwarding entry | - | 256 |
| 3. MAC filtering entry | 256 | 256 |
| 4. Cluster member | - | 24 |
| 5. IP routing domain | 128 | 128 |
| 6. IGMP Filtering entry | 256 | 256 |
| 7. IGMP MVR entry | - | 256 |
| 8. VRRP entry | - | 64 |
| 9. Protocol based VLAN entries per port | - | 7 |
| 10. Port-security max address-limit number | 32k | 32k |
| 11. DHCP Server | - | 16 |
| 12. Syslog server entry | 2 | 4 |
| 13. IP source guard entry | 128 | 1k |
| 14. IP subnet based VLAN entry | - | 16 |
| 15. MVR VLAN entry | - | 5 |
| 16. VLAN-stacking Selective QinQ entry | - | 1k |
| 17. VLAN -mapping entry | - | 1k |
| 18. MAC table | 32k | 32k |
| 19. Routing table | 2k | 2k |
| 20. DHCP snooping binding table | - | 16k |
| 21. Multicast group | 1k | 1k |
| 22. ACL | 128 | 512 |
| 23. Policy route | - | 64 |
| 24. DHCP option 82 profile | - | 130 |
| 25. Remote port monitoring vlan | - | 10 |
| 26. Static ARP entry | - | 256 |
| 27. Static route max entry | 64 | 64 |
| 28. MAC-based VLAN | - | 1k |

| Limitation of Setting | Cloud | Standalone |
|---|--------------|-------------------|
| 29. Voice VLAN OUI entry | 6 | 10 |
| 30. ZON neighbor per-port maximum clients | - | 10 |
| 31. IPv6 Source Guard binding table | - | 100 |
| 32. Queue | 6 | 8 |

Change History

- V4.80(AMBL.0) | 07/15/2022
- V4.70(AMBL.1) | 03/23/2021
- V4.70(AMBL.0) | 10/12/2020
- V4.60(AMBL.3) | 09/12/2019
- V4.60(AMBL.2) | 05/30/2019
- V4.60(AMBL.1) | 01/04/2019