



## **Ruijie RG-EAP and RG-RAP Series Access Points Release Notes, AP\_3.0(1)B2P55&AP\_3.0(1)B11P55**

---

Release Date: July 10, 2021

# Contents

This document includes the following sections:

- [Basic Information](#)
- [Hardware Supported](#)
- [New Features](#)
- [Fixed Bugs](#)
- [Upgrade Files](#)
- [Upgrade Tips](#)

## Basic Information

Table 1 Basic Information of the Current Release

<b>Version Number</b>	AP_3.0(1)B2P55&AP_3.0(1)B11P55
<b>Applicable Product</b>	QCA Access Points: RG-EAP602 v1.00 RG-EAP602 v2.00  MTK Access Points: RAP2200(E) v1.00 RAP2200(F) v1.00 RAP1200(F) v1.00 RAP1200(P) v1.00
<b>Category</b>	Official Release

## Hardware Supported

Table 2 Hardware Models

Hardware Model	Version	Description
RG-EAP602	1.00/2.00	Outdoor access point, 2.4 GHz dual streams, 5.8 GHz dual streams, 802.11b/g/n and 802.11a/n/ac
RG-RAP2200(E)	1.00	Indoor access point, 2.4 GHz dual streams, 5.8 GHz dual streams, 802.11b/g/n and 802.11a/n/ac. The wired port supports a rate of 1000Mbps.
RG-RAP2200(F)	1.00	Indoor access point, 2.4 GHz dual streams, 5.8 GHz dual streams, 802.11b/g/n and 802.11a/n/ac. The wired port

		supports a rate of 100Mbps.
RG-RAP1200(F)	1.00	Panel-type access point, 2.4 GHz dual streams, 5.8 GHz dual streams, 802.11b/g/n and 802.11a/n/ac. The wired port supports a rate of 100Mbps.
RG-RAP1200(P)	1.00	Panel-type access point, 2.4 GHz dual streams, 5.8 GHz dual streams, 802.11b/g/n and 802.11a/n/ac. The wired port supports a rate of 1000Mbps. Support PoE output to 802.3 AF-compliant PD.



**Note** For details, see Ruijie RG-RAP and RG-EAP Series Access Points Hardware Installation and Reference Guide.

## New Features

This section describes the new features.

### SSID-based Whitelist/Blacklist

<b>Feature</b>	SSID-based whitelist and blacklist are supported.
<b>CLI Command</b>	N/A
<b>Required Release</b>	OW3.0(1)B2P32 or later

### OUI-based Whitelist/Blacklist

<b>Feature</b>	OUI-based whitelist and blacklist are supported
<b>CLI Command</b>	N/A
<b>Required Release</b>	OW3.0(1)B2P32 or later

### Band Steering

<b>Feature</b>	Band steering is supported.
<b>CLI Command</b>	N/A
<b>Required Release</b>	OW3.0(1)B2P32 or later

### Load Balancing

<b>Feature</b>	Load balancing is supported.
<b>CLI Command</b>	N/A

<b>Required Release</b>	OW3.0(1)B2P32 or later
-------------------------	------------------------

**AP VLAN Port**

<b>Feature</b>	All new Wi-Fi networks work in bridge mode by default.
<b>CLI Command</b>	N/A
<b>Required Release</b>	OW3.0(1)B2P32 or later

**WIO**

<b>Feature</b>	WIO is supported.
<b>CLI Command</b>	N/A
<b>Required Release</b>	OW3.0(1)B2P55 or later

**Wifi6 switch**

<b>Feature</b>	Wifi6 switch is supported.
<b>CLI Command</b>	N/A
<b>Required Release</b>	OW3.0(1)B2P55 or later

**Encryption type**

<b>Feature</b>	Encryption type is same as enterprise AP, Support roaming switch with enterprise AP.
<b>CLI Command</b>	N/A
<b>Required Release</b>	OW3.0(1)B2P55 or later

**New countries**

<b>Feature</b>	New country code: Tunisia(TN)、Cyprus(CY)、Albania(AL).
<b>CLI Command</b>	N/A
<b>Required Release</b>	OW3.0(1)B2P55 or later

## Fixed Bugs

Table 3 Fixed Bugs

No.	Bug Description
1	An error occurred to the management frame power when the access point was upgraded.
2	Click an ES series switch on the switch management page, and the "401 authentication failed." Message would appear.
3	Disable the function of sending DHCP Discover message periodically.

4	Solve the problem caused by the timeout of APP deployment. Affected area: all products.
---	---

## Upgrade Files


Table 4 Upgrade File

Applicable Model	Upgrade File	File Size	MD5
RG-EAP602 v1.00	AP_3.0(1)B2P55_EAP602_08190602.tar.gz	7,735,331 bytes	15FFCDD184713B840369A5E
RG-EAP602 v2.00			AE27FB78B
RAP2200(E) v1.00	AP_3.0(1)B11P55_EAP212(G)_08190602.tar.gz	6,960,774 bytes	7B8CAF16BCA1388346C2CC8
RAP2200(F) v1.00			4234707DC
RAP1200(F) v1.00	AP_3.0(1)B11P55_EAP212(F)_08190602.tar.gz	6,953,701 bytes	B976F0CA6BD1A9753B53B4A
RAP1200(P) v1.00			C56CDA0AA
	AP_3.0(1)B11P55_RAP1200(P)_08190602.tar.gz	6,844,915 bytes	12D58701A3D85AF962605488
			78B23FAE

## Upgrade Tips

The following are some tips for upgrading:

- There is no need to upgrade BOOT.
- The RG-EAP and RG-RAP series access points can be upgraded on both Web and Ruijie Cloud. This document only introduces upgrade steps on Web.
- The RG-EAP and RG-RAP series access points can be upgraded on Web, including local upgrade and online upgrade. This document only introduces local upgrade.
- During the upgrade, pay attention to the prompt messages. If failures occur, please save the log and contact us for technical assistance.
- During the upgrade, it is recommended you not power off or reset the system, or plug/unplug any module.

 Wait a few minutes after upgrade finishes and log into Web to check whether the device is upgraded to the target version. For details, please see *Ruijie RG-EAP and RG-RAP series access points Web-Based Configuration Guide*.