

LTE7490-M904

Generic Version

Firmware Release Note

V1.00(ABQY.3)C0

Date:	Mar. 14, 2022
Author:	Aaron Kuo
Reviewer:	Perry Lin

THIS DOCUMENT CONTAINS PROPRIETARY TECHNICAL INFORMATION THAT IS THE PROPERTY OF THE ZYXEL AND SHOULD NOT BE DISCLOSED TO OTHERS IN WHOLE OR IN PART, REPRODUCED, COPIED, OR USED AS BASIS FOR DESIGN, MANUFACTURING OR SALE OF APPARATUS WITHOUT WRITTEN PERMISSION OF ZYXEL.

TABLE OF CONTENTS

REVISION HISTORY 3

SUPPORTED PLATFORMS:..... 4

VERSIONS: 4

FIRMWARE IMAGE INFORMATION:..... 4

NOTES: 4

MODIFICATIONS IN V1.00(ABQY.3)C0..... 4

MODIFICATIONS IN V1.00(ABQY.2)C0..... 6

MODIFICATIONS IN V1.00(ABQY.1)C0..... 6

MODIFICATIONS IN V1.00(ABQY.0)C0..... 6

Revision History

Date	Release	Author	Description
2020/02/10	1.0	Marcus Tsai	V1.00(ABQY.0)C0 FW release
2020/08/22	2.0	YuChih Hu	V1.00(ABQY.1)C0 FW release
2020/09/07	3.0	YuChih Hu	V1.00(ABQY.2)C0 FW release
2022/03/14	4.0	Aaron Kuo	V1.00(ABQY.3)C0 FW release

ZyXEL LTE7490-M904 Generic V1.00(ABQY.3)C0

Release Note

Date: Mar. 14, 2022

Supported Platforms:

ZyXEL LTE7490_M904 Generic (EU)

Versions:

Firmware version : V1.00(ABQY.3)C0

Firmware image information:

Image	Version	File name	MD5 sum
FW Image	V1.00 (ABQY.3)C0	100ABQY3C0.bin	59f9c8a14de4639a09e53bec8f37f67e

Notes:

NA

Modifications in V1.00(ABQY.3)C0

[Know defects]

N/A

[Feature Enhancement/Configuration Changing]

1. Add the solution of slow webpage loading
2. Upgrade Dnsmasq Version to 2.78
3. Upgrade OpenSSL Version to 1.1.1b
4. Add DHCP relay feature
5. TR-069 is disabled by default

[Fixed Defects]

1. MTK WiFi Frag Defrag attack

Modifications in V1.00(ABQY.2)C0

[Know defects]

N/A

[Feature Enhancement/Configuration Changing]

N/A

[Fixed Defects]

Improve auto APN mechanism.

Modifications in V1.00(ABQY.1)C0

[Know defects]

N/A

[Feature Enhancement/Configuration Changing]

N/A

[Fixed Defects]

1. Improve the connection mechanism when signal strength adjustment.

Modifications in V1.00(ABQY.0)C0

First release