



Access Points Release Note

Firmware V6.29 Patch 1

Date: November 14, 2022

Zyxel Access Points

V6.29(P1)C0 Release Note

Overview

This document provides firmware release information on Zyxel Access Points platforms, introduce new Access Points, new features and enhancements, bug fix, known issues and workarounds information for Release V6.29 Patch1 C0.

Supported Platforms

- NWA50AX V6.29(ABYW.1)
- NWA55AXE V6.29(ABZL.1)
- NWA90AX V6.29(ACCV.1)

New Features and Enhancements

1. PSK can be customized per AP basis when Programmable SSID is enabled. (Nebula Pro Pack license is required)
2. Smart Mesh added 3 advanced capabilities – manual uplink, disable downlink, re-connect. (Cloud mode only)
3. Smart Steering added optimization aggressiveness for disassociation.
4. NAT mode is added to NWA50AX/55AXE/90AX. (Cloud mode only)
5. Layer 2 isolation is added to NWA50AX/55AXE; NWA90AX has this already.

Bug fix

Bug fix \ Mode	Cloud	Managed	Standalone
1. [eITS: 220101169] [Symptom] Local GUI port usage display issue from the path: Monitor >> Network status >> Port Statistics Table >> Switch To Graphic View			V
2. [eITS: 220700979] [Symptom] iPhone can't connect to the SSID automatically, and when tap on SSID, got the incorrect password although password is correct	V		V
3. [eITS: 220800835] [Symptom] AP offline on Nebula and show port 4335 blocked message on local web, when connect to mobile router LAN port	V		
4. [eITS: 220801383] [Symptom] Once a client disconnected, AP LED will turn into blue light even there are still other clients connected with	V		V
5. [eITS: 221001403] [Symptom] Random restart of APs in a particular scenario	V		V

Known Issue

N/A

Limitation of Settings:

N/A