Zyxel

Access Points Release Note

Firmware V6.25 Patch 6

Date: March 10, 2021

Zyxel Access Points

V6.25(P6)C0 Release Note

Overview

This document provides firmware release information on Zyxel Access Points platforms, new features and enhancements, bug fix, known issues and workarounds information for Release V6.25 Patch6 C0.

Supported Platforms

- NWA1123-AC HD V6.25(ABIN.6)
- NWA1302-AC V6.25(ABKU.6)
- NWA5123-AC HD V6.25(ABIM.6)
- WAC5302D-Sv2 V6.25(ABVZ.6)
- WAC6303D-S V6.25(ABGL.6)

New Features and Enhancements

N/A

Bug fix

Mode / Bug fix	Cloud	Managed	Standalone
1. [Symptom] AP may not send traffic on specific VLANs while the uplink port is link down more than 3 minutes in Continuous PoE switch deployment.	V		

Known Issue

Mode / Known Issue	Cloud	Managed	Standalone
1. [eITS: 210400642] [Symptom] Mesh SSID is visible	V		
2. [eITS: 210500147] [Symptom] SSID not broadcast after changing the forwarding mode from NAT to local bridge	V		
3. [eITS: 210900596] [Symptom] Act-session ID in access stage is different to accounting stage	V	V	V

Limitation of Settings:

N/A