ZYXEL

Zyxel

Firmware Release Note

ARMOR G1

NBG6818

Release V1.00(ABSC.6)C0

Armor G1 NBG6818
Release V1.00(ABSC.6)C0
Release Notes

Date: July, 01, 2022

Supported Platforms:

Zyxel NBG6818

Release Package:

File name	
V1.00(ABSC.6)C0.bin	NBG6818 Firmware Package
V1.00(ABSC.6)C0.bin	NBG6818 Firmware Package

Product information:

Enhancement in V1.00(ABSC.6)C0| 07/01/2022

[Enhancement]

● Upgrade PCloud's XMPP feature rootCA.

[BugFix]

● In WLAN guest SSID include space, then DUT not issue beacon.
● The USB capacity show `NaN%` when if USB disk has been plugged into the DUT then change the operating mode or reboot the DUT.
● Openssl 1.0.2h hotfix.

Enhancement in V1.00(ABSC.5)C0| 09/30/2021

[Enhancement]

● Upgrade dnsmasq to 2.83
● Upgrade Tuxera NTFS kernel module to 3021.4.15.8
● Update WiFi code for FragAttacks against WiFi products issues.
● Update DUT's root password process for root access of the device.
● Add debug firmware upgrade page and remove SSH remote.

[Bug Fix]

● Armor G1 and Armor G5 not able to create DDNS.
● SSID can't broadcast if Wifi blocked between 00:00 - 07:00 and reboot Armor G1.

ZYXEL

- As NBG6818 is Bridge Mode the host name is NONE
- After set DMZ the IPTV can not work fine
- WiFi name can`t display in GUI.

Enhancement in V1.00(ABSC.4)C0| 09/22/2020

[Enhancement]

- Add Russian and Chinese into GUI.

[Bug Fix]

- GUI > Settings > System > Export log, then diagnose.log is no any log.

Enhancement in V1.00(ABSC.3)C0| 08/08/2020

[Bug Fix]

- Diagnose > Speed Test > Tap Test, then get stuck in the upload.

Enhancement in V1.00(ABSC.2)C0| 02/05/2020

[Initial Version]