

ZYXEL

Software Release Note Switch GS1200-8HPv2

Date: Oct. 28, 2022

Zyxel Switch GS1200-8HPv2

V2.00(ABMF.2)C0 Release Note

Date: Oct. 28, 2022

This document describes the features in the GS1200-8HPv2 product for its V2.00(ABMF.2)C0 release. Firmware upgrades may reset configuration options to factory default. Please backup your current configuration first before performing firmware upgrade.

Supported Platforms

Support Platform	Firmware version
Zyxel GS1200-8HPv2	V2.00(ABMF.2)C0

New Feature and Enhancements

None

Bug fix

1. [Vulnerability] Vulnerability protection for timing side-channel attack.
2. [eITS#220201161] When modifying existing VLAN configuration, the PVID of ports may reset to 0 automatically.
3. [eITS#221000214] Adjust the port limit to prevent ARP packet be drop.
4. [eITS#220900548] Change any setting then click apply button twice rapidly on Link-aggregation, Port mirroring, and Port isolation page will cause switch back to previous configuration.
5. While enabling Port Mirroring, apply button will not be clickable.

Known Issue

1. After firmware upgrade process is completed, switch will not redirect to login page automatically. User needs to re-type switch management IP in browser URL to access login page.
2. Downgrade firmware from V1.00 patch 5 to V1.00 patch 4 and below versions will cause admin account unable to login. In the unlikely event of downgrading firmware, resetting to default can then login with default account and password.
3. Firmware V2.00 patch 1 strengthen user security by supporting case sensitive for user password and with additional enhancement on password encryption algorithm. In the event of downgrading firmware to prior versions, switch will need to be reset and login with default password.

Change History

- V2.00(ABMF.2) | 10/28/2022
- V2.00(ABMF.1) | 09/01/2021
- V2.00(ABMF.0) | 12/17/2020
- V1.00(ABxx.4) | 01/10/2019
- V1.00(ABxx.3) | 11/10/2018
- V1.00(ABxx.2) | 10/25/2018
- V1.00(ABxx.1) | 07/27/2018
- V1.00(ABxx.0) | 11/08/2017