

Zyxel Switch GS1200-8HPv2

V2.00(ABMF.0)C0 Release Note

Date: Dec. 17, 2020

This document describes the features in the GS1200-8HPv2 product for its V2.00(ABMF.0)C0 release. Firmware upgrades may reset configuration options to factory default. Please backup your current configuration first before performing firmware upgrade.

Supported Platforms

Support Platform	Firmware version
Zyxel GS1200-8HPv2	V2.00(ABMF.0)C0

New Feature and Enhancements

1. Support port isolation
2. Support bandwidth control
3. Support management VLAN
4. Support system up time

Bug fix

V1.00(ABMF.5)C0

1. eITS#200700086
[\[IGMP\]](#)IGMP control packet causes loop

Known Issue

1. [\[Firmware\]](#) Downgrade from V1.00 patch 4 to V1.00 patch 3 and below versions will cause admin account unable to login. In the unlikely event of downgrading firmware, resetting to default can then login with default account and password.

Change History

- V2.00(ABMF.0) | 12/17/2020
- V1.00(ABxx.4) | 01/10/2019
- V1.00(ABxx.3) | 11/10/2018
- V1.00(ABxx.2) | 10/25/2018
- V1.00(ABxx.1) | 07/27/2018
- V1.00(ABxx.0) | 11/08/2017