

Zyxel

Nebula NR7101 Release Note Firmware V1.15 Patch 1

Date: November 4, 2022

Zyxel Nebula NR7101

V1.15(P1)C0 Release Note

Overview

This document provides firmware release information on Zyxel NR7101, new features and enhancements, bug fix, known issues and workarounds information for Release V1.15 Patch1 C0.

This Firmware is for Nebula NR7101 only (Part Number: NR7101-EUZNN1F), NOT for on premise models.

Model	Part Number	Description
NR7101	NR7101-EU01V1F	5G NR Outdoor Router
Nebula NR7101	NR7101-EUZNN1F	Nebula cloud-managed 5G NR Outdoor Router

Supported Platforms

- Nebula NR7101 V1.15(ACCC.1)C0

New Features and Enhancements

1. Support dual SIM card on NR7101

.

Bug fix

1. [SPR# 220322433] Internet circle add Gateway IP conflict event
2. [SPR# 220614374] download from Nebula ca cert fail
3. [SPR# 220125130] There is no "Nebula" option in 5G route Log category scroll menu and active log in log setting
4. [SPR# 220401062] Assign the same IP to different devices
5. [SPR# 220401062] DHCP pool can't be modified
6. [SPR# 220401062] Static DHCP pool not work

7. [SPR# 220831547] No log shown in Local GU > system monitor > log page

Known Issue

1. DHCPv6 relay function fails

Limitation of Settings:

N/A

Default Setting:

1. Account for GUI:

Username	Password
Admin	Refer to device back label

2. Default URL: <http://192.168.1.1> is for the device GUI login