

Zyxel

Access Points Release Note Firmware V6.25 Patch 9

Date: April 11, 2022

Zyxel Access Points

V6.25(P9)C0 Release Note

Overview

This document provides firmware release information on Zyxel Access Points platforms, introduce new Access Points, new features and enhancements, bug fix, known issues and workarounds information for Release V6.25 Patch9 C0.

Supported Platforms

- NWA1123-AC HD V6.25(ABIN.9)
- NWA1302-AC V6.25(ABKU.9)
- NWA5123-AC HD V6.25(ABIM.9)
- WAC5302D-Sv2 V6.25(ABVZ.9)
- WAC6303D-S V6.25(ABGL.9)

New Features and Enhancements

N/A

Bug fix

Bug fix	Mode	Cloud	Managed	Standalone
1. [eITS: 220201107, 220300976] [Symptom] AP reboot itself due to unable to handle null pointer. (free skb for NULL ctfpool)		V	V	V
2. [eITS: 220101546] [Symptom] AP reboot itself due to error handling on netfiler		V	V	V
3. [eITS: 201200268] [Symptom] AP reboot itself due to error on AMPDU setting		V	V	V
4. [eITS: 220201132] [Symptom] AP reboot itself due to NAS CoreDump		V	V	V
5. [Vulnerability] Fix vulnerabilities CVE-2022-26531 and CVE-2022-26532		V	V	V

Known Issue

Mode Known Issue	Cloud	Managed	Standalone
1. [eITS: 210400642] [Symptom] Mesh SSID is visible	V		
2. [eITS: 210500147] [Symptom] SSID not broadcast after changing the forwarding mode from NAT to local bridge	V		
3. [eITS: 210900596] [Symptom] Act-session ID in access stage is different to accounting stage	V	V	V

Limitation of Settings:

N/A