

# **LTE7490-M904**

## **Generic Version**

Firmware Release Note

1.00(ABQY.4)C0

Date: Sep. 21, 2022

Author: Aaron Kuo

Reviewer: Perry Lin

**THIS DOCUMENT CONTAINS PROPRIETARY TECHNICAL INFORMATION THAT IS THE PROPERTY OF THE ZyXEL AND SHOULD NOT BE DISCLOSED TO OTHERS IN WHOLE OR IN PART, REPRODUCED, COPIED, OR USED AS BASIS FOR DESIGN, MANUFACTURING OR SALE OF APPARATUS WITHOUT WRITTEN PERMISSION OF ZyXEL.**

TABLE OF CONTENTS

REVISION HISTORY ..... 3

SUPPORTED PLATFORMS:..... 4

VERSIONS: ..... 4

FIRMWARE IMAGE INFORMATION:..... 4

NOTES: ..... 4

MODIFICATIONS IN 1.00(ABQY.4)C0 ..... 4

MODIFICATIONS IN 1.00(ABQY.3)C0 ..... 5

MODIFICATIONS IN 1.00(ABQY.2)C0 ..... 5

MODIFICATIONS IN 1.00(ABQY.1)C0 ..... 5

MODIFICATIONS IN 1.00(ABQY.0)C0 ..... 6

## Revision History

Date	Release	Author	Description
2020/02/10	1.0	Marcus Tsai	V1.00(ABQY.0)C0 FW release
2020/08/22	2.0	YuChih Hu	V1.00(ABQY.1)C0 FW release
2020/09/07	3.0	YuChih Hu	V1.00(ABQY.2)C0 FW release
2022/03/14	4.0	Aaron Kuo	V1.00(ABQY.3)C0 FW release
2022/08/04	5.0	Aaron Kuo	V1.00(ABQY.4)C0 FW release

## ZyXEL LTE7490-M904 Generic 1.00(ABQY.4)C0

### Release Note

Date: Sep. 21, 2022

#### Supported Platforms:

ZyXEL LTE7490\_M904 Generic (EU)

#### Versions:

Firmware version : V1.00(ABQY.4)C0

#### Firmware image information:

Image	Version	File name	MD5 sum
FW Image	1.00 (ABQY.4)C0	100ABQY4C0.bin	b8c1bd4d1d7158d2915926e3442b1dee

#### Notes:

N/A

#### Modifications in 1.00(ABQY.4)C0

##### [Know defects]

N/A

##### [Feature Enhancement/Configuration Changing]

1. Update openssl version to 1.1.1n

##### [Fixed Defects]

1. Fix specific URL get cleartext storage of sensitive information

## **Modifications in 1.00(ABQY.3)C0**

### **[Know defects]**

N/A

### **[Feature Enhancement/Configuration Changing]**

1. Add the solution of slow webpage loading
2. Upgrade Dnsmasq Version to 2.78 with patched version.
3. Upgrade OpenSSL Version to 1.1.1b
4. Add DHCP relay feature
5. TR-069 is disabled by default

### **[Fixed Defects]**

Patch WiFi Frag Defrag attack

## **Modifications in 1.00(ABQY.2)C0**

### **[Know defects]**

N/A

### **[Feature Enhancement/Configuration Changing]**

N/A

### **[Fixed Defects]**

Improve auto APN mechanism.

## **Modifications in 1.00(ABQY.1)C0**

### **[Know defects]**

N/A

### **[Feature Enhancement/Configuration Changing]**

N/A

### **[Fixed Defects]**

1. Improve the connection mechanism when signal strength adjustment.

## **Modifications in 1.00(ABQY.0)C0**

First release.