



Access Points Release Note

Firmware V6.25 Patch 10

Date: June 22, 2022

Zyxel Access Points

V6.25(P10)C0 Release Note

Overview

This document provides firmware release information on Zyxel Access Points platforms, new features and enhancements, bug fix, known issues and workarounds information for Release V6.25 Patch10 C0.

Supported Platforms

- NWA50AX V6.25(ABYW.10)
- NWA55AXE V6.25(ABZL.10)

New Features and Enhancements

N/A

Bug fix

Bug fix \ Mode	Cloud	Managed	Standalone
1. [eITS: 220600088] [Symptom] Client cannot get IP address after enable smart mesh	V		V
2. [eITS: 220600090] [Symptom] Client cannot connect due to driver abnormal L2 update frame transmission	V		V

3. [eITS: 220400271] [Symptom] 5GHz channel width may be frozen in 20MHz even configure as 80MHz	V		V
4. [eITS: 220400958] [Symptom] NWA55AXE internet traffic not passed after reboot	V		V
5. [eITS: 211000989] [Symptom] NWA50AX not broadcast SSID due to openssl key issue	V		V
6. [eITS: 211201294] [Symptom] NWA50AX / port usage display issue	V		V
7. [eITS: 220400185] [Symptom] Station Fail connect to SSID with WPA2-Personal security method	V		V
8. [eITS: 220400302] [Symptom] Wi-Fi didn't turn off after shutdown NWA50AX			V
9. [eITS: 210901238] [Symptom] NWA50AX bootup failure	V		V
10. [eITS: 211101095] [Symptom] NWA55AXE wireless bridge failure	V		
11. [eITS: 211200588] [Symptom] Schedule SSID does not working properly	V		V
12. [eITS: 220200836] [Symptom] Low downlink data rate on 11ax radio mode	V		V
13. [eITS: 220600630] [Symptom] iOS device cannot connect SSID successful and display incorrect password	V		

Known Issue

Mode Known Issue	Cloud	Managed	Standalone
1. [eITS: 210400642] [Symptom] Mesh SSID is visible	V		
2. [eITS: 210900596] [Symptom] Act-session ID in access stage is different to accounting stage	V	V	V

Limitation of Settings:

N/A