



Access Points Release Note

Firmware V6.25 Patch 2

Date: October 21, 2021

Zyxel Access Points

V6.25(P2)C0 Release Note

Overview

This document provides firmware release information on Zyxel Access Points platforms, new features and enhancements, bug fix, known issues and workarounds information for Release V6.25 Patch2 C0.

Supported Platforms

- NAP203 V6.25(ABFA.2)
- NAP303 V6.25(ABEX.2)
- NAP353 V6.25(ABEY.2)
- NWA1123-AC HD V6.25(ABIN.2)
- NWA1123-AC PRO V6.25(ABHD.2)
- NWA1123-ACv3 V6.25(ABVT.2)
- NWA1302-AC V6.25(ABKU.2)
- NWA5123-AC HD V6.25(ABIM.2)
- WAC500 V6.25(ABVS.2)
- WAC500H V6.25(ABWA.2)
- WAC5302D-Sv2 V6.25(ABVZ.2)
- WAC6103D-I V6.25(AAXH.2)
- WAC6303D-S V6.25(ABGL.2)
- WAC6502D-E V6.25(AASD.2)
- WAC6502D-S V6.25(AASE.2)
- WAC6503D-S V6. 25(AASF.2)
- WAC6552D-S V6.25(ABIO.2)
- WAC6553D-E V6.25(AASG.2)
- NWA110AX V6.25(ABTG.2)
- NWA210AX V6.25(ABTD.2)
- WAX510D V6.25(ABTF.2)
- WAX610D V6.25(ABTE.2)
- WAX630S V6.25(ABZD.2)
- WAX650S V6.25(ABRM.2)

New Features and Enhancements

N/A

Bug fix

Accumulated bugs fixed.

Known Issue

Mode Known Issue	Cloud	Managed	Standalone
1. [eITS: 210400642] [Symptom] Mesh SSID is visible	V		
2. [eITS: 210500147] [Symptom] SSID not broadcast after changing the forwarding mode from NAT to local bridge	V		
3. [eITS: 210900596] [Symptom] Act-session ID in access stage is different to accounting stage	V	V	V

Limitation of Settings:

N/A