

# **LTE2566-M634**

## **Official Version**

### **Firmware Release Note**

V1.00(ABTW.3)C0

Date: Jan. 19<sup>th</sup> 2022  
Author: CT Yi  
Reviewer:

THIS DOCUMENT CONTAINS PROPRIETARY TECHNICAL INFORMATION THAT IS THE PROPERTY OF THE Zyxel AND SHOULD NOT BE DISCLOSED TO OTHERS IN WHOLE OR IN PART, REPRODUCED, COPIED, OR USED AS BASIS FOR DESIGN, MANUFACTURING OR SALE OF APPARATUS WITHOUT WRITTEN PERMISSION OF Zyxel.

TABLE OF CONTENTS

VERSIONS-V1.00(ABTW.3)C0: ..... 4

VERSIONS-V1.00(ABTW.2)C0: ..... 5

VERSIONS-V1.00(ABTW.1)C0: ..... 6

VERSIONS-V1.00(ABTW.0)C0: ..... 7

**REVISION HISTORY**

<b>Date</b>	<b>Release</b>	<b>Author</b>	<b>Description</b>
Apr 9th 2020	V1.00(ABTW.0)C0	Charles Chi	V1.00(ABTW.0)C0, First Release Note information
May 12 <sup>th</sup> 2020	V1.00(ABTW.1)C0	Charles Chi	Bug fixed.
Nov 13 <sup>th</sup> 2020	V1.00(ABTW.2)C0	Charles Chi	Bug fixed.
Jan. 19th 2022	V1.00(ABTW.3)C0	CT Yi	Defect fixed.

# **Zyxel LTE2566-M634 Official V1.00(ABTW.3)C0 Release Note**

Date: Sep. 9<sup>th</sup> 2021

## **Supported Platforms:**

Zyxel LTE2566-M634

## **Versions-V1.00(ABTW.3)C0:**

Firmware version : V1.00(ABTW.3 )C0

## **MD5 checksum :**

MD5 checksum : 3c9aaa528e7c6421acd4aa5035e41e3c

## **Feature Enchantment/Configuration Change**

1. Fix APN auto auth. method defect for PAP or CHAP
2. Fix remote MGMT defect

## **Known Defect**

N/A

## **Zyxel LTE2566-M634 Official V1.00(ABTW.2)C0 Release Note**

Date: Nov 13<sup>th</sup> 2020

### **Supported Platforms:**

Zyxel LTE2566-M634

### **Versions-V1.00(ABTW.2)C0:**

Firmware version : V1.00(ABTW.2)C0

### **MD5 checksum :**

MD5 checksum : a6a3eaea423d831d3042bf45aa4453ea

### **Feature Enchantment/Configuration Change**

1. Bug fixed on OLED display contents
2. Auto APN function enhancement
3. TimeZone setting update for Russia

### **Known Defect**

N/A

## **Zyxel LTE2566-M634 Official V1.00(ABTW.1)C0 Release Note**

Date: May 12<sup>th</sup> 2020

### **Supported Platforms:**

Zyxel LTE2566-M634

### **Versions-V1.00(ABTW.1)C0:**

Firmware version:V1.00(ABTW.1)C0

### **MD5 checksum:**

MD5 checksum : 9ebc741dd88e29c338dec6e0ca85103b

### **Feature Enchantment/Configuration Change**

1. OLED display issue
2. SPN display improvement
3. Minor bugs fixed

### **Known Defect**

NA

## **Zyxel LTE2566-M634 Official V1.00(ABTW.0)C0 Release Note**

Date: Apr 9<sup>th</sup> 2020

### **Supported Platforms:**

Zyxel LTE2566-M634

### **Versions-V1.00(ABTW.0)C0:**

Firmware version:V1.00(ABTW.0)C0

### **MD5 checksum:**

MD5 checksum : 21C5EBE5210CA057F7C429ACEDEBD7BE

### **Feature Enchantment/Configuration Change**

NA

### **Known Defect**

1. SMS web GUI, the Create wording doesn't translate to Russian.
2. When power off and user press power button, the LCD screen doesn't show Battery Status.
3. When device at CA condition, the LCD screen doesn't display 4G+ icon.