

## Zyxel Firmware Release Note

**Model Name:** WRE2206

**Release Version:** V1.00(AAVZ.3)C0\_20171115

**Release Date:** Nov 16, 2017

### Notes

This is a hotfix intended to resolve a specific problem before the standard solution firmware becomes available. Feel free to download it, but please be aware that this firmware has not gone through full software quality assurance testing. Only apply it to the devices that are experiencing the specific problem, and install the standard firmware when it becomes available.

### Product information

Default LAN IP: 192.168.1.2

Default username: admin

Default password: 1234

Firmware upgrade may reset the repeater's configuration to the factory default. Before performing an upgrade, please backup your current setting first.

Known Issues:

N/A

### Modification in V1.00(AAVZ.3)C0\_20171115 | Nov/16/2017

Fix WPA2 KRACK vulnerability

### Modification in V1.00(AAVZ.3)C0 | June/19/2017

AP signal strength LED behavior Incorrect

### Modification in V1.00(AAVZ.2)C0 | April/28/2015

Fulfill the requirement for CE Adaptively test

### Modification in V1.00(ABDU.1)C0 | April/22/2015

Initial release